

POSSIBLE REPAIRS TO DO BEFORE SLIPLINE CAN BE DONE

SUBDIVISION	ADDRESS	PROJECT NUMBER	DEG 1-10	MH#	MH#	REPAIR NEEDED	FT LOC	STATUS	TV DONE
Broadview	Concord Green Apts		Normal	15-49	15-47	Jnt crk at bottom/mod dirt	191.0	Not Bid	8/2/2012
Broadview II	Pine Dr		Normal	15-64	15-Stub17	Prot tap 1/2 into main, rts @ con 60%	132.0	Not Bid	9/17/2012
Broadview	7688 Meadow		Normal	15-172	15-171	Hammer tap L 9:00	244.00	Not Bid	07/11/11
Broadview B	Meadow Lane		Normal	15-177	15-178	Lateral connection problem	320.5	Not Bid	10/31/2014
Broadview B	8000 Meadow	08-194	Emergency	15-211	11-277	Bad tap/roots	63.8	Not Bid	2/20/2008
Broadview B	Ridgemont (need #)	08-195	High	15-211	11-277	Tap,R,8" line offset	144.0	Not Bid	2/20/2008
Broadview B	8044 Meadow	08-196	High	15-211	11-277	Old rep, tap, offset jnt	225-252	Not Bid	2/20/2008
Broadview B	8044 Meadow	08-197	Emergency	15-211	11-277	Tap, L, roots	281.3	Not Bid	2/20/2008
Broadview B	8088 Meadow	08-198	Emergency	15-211	11-277	Tap, L, roots	387.0	Not Bid	2/20/2008
Broadview B	7972 Ridgemont	08-73	Normal	15-212	15-211	Tap, right, roots/hvy	296.5	Not Bid	8/23/2007
Broadview B	7988 Meadow	08-74	Normal	15-211	15-212	Tap, right separate	75.9	Not Bid	8/24/2007
Buslers	4055 apt A Pine Drive		Normal	15-223	15-25	Separate jnt, water	2.0	Not Bid	3/26/2010
Busler's/Pine Dr	4011 Pine Dr	08-225	Normal	15-223	15-25	Hammer tap	89.9	Not Bid	3/18/2008 3/26/2010
Busler's/Pine Dr	4011 Pine Dr	08-226	Normal	15-223	15-25	Hammer tap	91.7	Not Bid	3/18/2008 3/26/2010
Colonial Hills	10688 Monticello		Normal	02-68	02-67	Hammer tap 10:00	108.5	Not Bid	12/17/2009
Colonial Hills	10722 Monticello		Normal	02-68	02-67	Hammer tap 10:00	294.4	Not Bid	12/17/2009
Colonial Hills	10733 Gettysburg	08-77	Normal	02-68	02-67	Hammer tap 2:00	328.0	Not Bid	12/17/09
Colonial Hills	10733 Gettysburg		Normal	02-68	02-67	2" Hole in main	357.7	Not Bid	12/17/2009
Colonial Hills	10600 Monticello 10611 Gettysburg		Normal	02-69	02-68	Hammer tap, 10:00, rts Hammer tap, 12:00, rts	44.6 48.0	Not Bid	12/17/2009
Colonial Hills	10633 Gettysburg		Normal	02-69	02-68	Hammer tap, 2:00, rts	145.4	Done by Hydromax on 12/31/14 Project 14-50	42/47/2009
Colonial Hills	10622 Monticello		Normal	02-69	02-68	Hammer tap L 10:00, rts	154.0	Done by Hydromax on 12/31/14 Project 14-50	42/47/2009
Colonial Hills	10644 Monticello		Normal	02-69	02-68	HT L 10:00, rts & crk	254.0	Not Bid	12/17/2009
Colonial Hills	10655 Gettysburg		Normal	02-69	02-68	HT R 2:00, water	263.0	Not Bid	12/17/2009
Colonial Hills	10666 Monticello		Normal	02-69	02-68	HT 12:00, water	326.0	Not Bid	12/17/2009
Colonial Hills	10877 Williamsburg Ct	08-79	Normal	02-71	02-67	Tap, top, roots/lgt	81.0	Not Bid	12/9/2009
Colonial Hills	10833 Williamsburg	10-09	Normal	02-71	02-67	Hammer tap, 12:00	276.0	Bid in 3/2010	12/9/2009
Colonial Hills	10677 Williamsburg Dr	08-163	Normal	02-178	02-177	Offset jnt & tap	30.0 33-36	Repair & Slipline Not Bid	1/24/2008 4/17/10
Colonial Hills	10655 Williamsburg Dr		Normal	02-178	02-177	Hammer tap L 10:00	151.0	Not Bid	4/17/2010
Colonial Hills	10611 Williamsburg Dr		Normal	02-178	02-177	Hammer tap L 10:00	332.0	Not Bid	4/17/2010
Franklin Place	Scenic Drive		Normal	15-179	15-180	Lateral connection problem	61.1	Not Bid	3/12/2014
Franklin Place	Meadow Lane		Normal	15-180	15-Stub23	Lateral connection problem	85.0	Not Bid	10/24/2014
Franklin Place	Meadow Lane		Normal	15-180	15-Stub23	Lateral connection problem	147.9	Not Bid	10/24/2014
Franklin Place	Meadow Lane		Normal	15-180	15-Stub23	Lateral connection problem	184.7	Not Bid	10/24/2014
Green Springs Valley	8499 Sycamore	08-173	Emergency	11-197	11-196	Tap, roots/hvy	88.8	Not Bid	2/4/2008
Green Springs Valley	4588 Stonegate (hse in Stonegate/line in back yd)	08-174	Emergency	11-197	11-196	Tap, roots/hvy	141.5	Not Bid	2/4/2008
Green Springs Valley	4622 Elm Dr	08-168	Emergency	11-215	11-216	Crack in pipe	31.2	Not Bid	2/4/2008
Green Springs Valley	4600 Elm Dr	08-169	High	11-215	11-216	RIJ, hvy	186.1	Not Bid	2/4/2008
Green Springs Valley	4588 Elm Dr	08-170	Emergency	11-215	11-216	Tap, R, offset & crack	325.2	Not Bid	2/4/2008
Green Springs Valley	4566 Elm Dr	08-171	Emergency	11-215	11-216	Tap, R, crack in line	416.6	Not Bid	2/4/2008
Green Springs Valley	4555 Elm Dr	08-172	High	11-215	11-216	Offset pipe at MH	421.6	Not Bid	2/4/2008
Green Spring Valley	8288 Oak	08-222	High	11-228	11-210	Tap, R, roots	121.9	Not Bid	2/7/2008
Green Spring Valley	8099 Chestnut		Normal	11-232	11-231	Bad tap L 9:00, roots	36.7	Not Bid	11/10/2009
Green Spring Valley	8077 Chestnut		Normal	11-232	11-231	Ham tap, L 9:00	108.6	Not Bid	11/10/2009
Green Spring Valley	8044 Lincoln Ave		Normal	11-232	11-231	Ham tap, R 1:00	205.7	Not Bid	11/10/2009
Green Spring Valley	8011 Lincoln Ave		Normal	11-232	11-231	Point repair (290' - 316) & 4 taps	290.5 - 316	Not Bid	11/10/2009
Green Spring Valley	8255 Chestnut		Normal	11-235	11-234	Protruding tap L 9:00	109.3	Not Bid	11/20/2009
Green Spring Valley	8222 Lincoln		Normal	11-235	11-234	Protruding tap R 3:00	217.4	Not Bid	11/20/2009
Green Spring Valley	8211 Chestnut		Normal	11-235	11-234	Protruding tap L 10:00	280.7	Not Bid	11/20/2009
Green Springs Valley	8277 N Larch Pl	08-192	Normal	11-249	11-261	Belly stop/pipe cracked	271.8	Not Bid	2/20/2008

SUBDIVISION	ADDRESS	PROJECT NUMBER	DEG 1-10	MH#	MH#	REPAIR NEEDED	FT LOC	STATUS	TV DONE
Green Springs Valley	Larch Place N		Normal	11-252	11-255	Lateral connection problem	96.3	Not Bid	9/9/2013
Green Springs Valley	Larch Place N		Normal	11-252	11-255	Lateral connection problem	191.2	Not Bid	9/9/2013
Green Springs Valley	Larch Place N		Normal	11-252	11-255	Lateral connection problem	361.4	Not Bid	9/9/2013
Green Springs Valley	8066 Birch Drive	N/A	Normal	11-256	11-257	Hammer tap, roots	243.4	Not bid/DVD 09-14	5/4/2009
Green Springs Valley	8088 Birch Drive	N/A	Normal	11-256	11-257	Tap, R, roots hvly	307.0	Not bid/DVD 09-14	5/4/2009
Green Spring Valley	8122 Birch Dr	08-81	Normal	11-257	11-256	Bad tap, roots/hvly	39.9	Bid 2/22/08 Not approved Will need rebid	8/31/2007 5/4/2009
Green Spring Valley	8044 Birch Dr	08-83	Normal	11-257	11-256	Tap, left, roots/hvly	402.5	Bid 2/22/08 Not approved Will need rebid	8/28/2007 5/4/2009
Green Spring Valley	8244 Chestnut	08-84	Normal	11-261	11-263	Hammer tap	86.7	Not Bid	6/6/2007
Heritage	Jamestown Dr		Normal	20-172	20-171	Lateral connection problem	29.7	Not Bid	4/22/2014
Heritage	Jamestown Dr		Normal	20-172	20-171	Lateral connection problem	93.4	Not Bid	4/22/2014
Heritage	6777 Heritage Dr		Normal	20-173	21-62	Bad tap inside MH, dirt	244.0	Not Bid	7/26/2011
Heritage Hills	6511 Heritage Dr	08-86	Normal	21-53	21-52	Tap, L, roots/lt	63.1	Not Bid	6/14/2007
Highway 261	Hwy 261		Normal	16-33A	16-33	Lateral connection problem	127.2	Not Bid	6/18/2014
Hillside	8888 Hillside Dr	08-96	Normal	11-46	11-45	Tap, top, roots/lt	28.4	Not Bid	11/16/2007
Hillview	7366 Lenn		Normal	15-143	15-142	Protruding tap 1"	131.0	Not Bid	4/23/2009
Hillview	7388 Lenn		Normal	15-143	15-142	Hammer tap, roots	218.0	Not Bid	4/23/2009
Hillview	7400 Lenn		Normal	15-143	15-142	PT 3" & RIJ severe	315 jnt 323 tap	Not Bid	4/22/2009 4/23/2009
Kenosha Hills	4877 Fond Du Lac		Normal	03-06	02-107	Tap repair	33.0	Not bid	5/7/2010
Kenosha Hills	4877 Fond Du Lac		Normal	03-06	02-107	Tap repair	91.7	Not bid	5/7/2010
Kenosha Hills	4877 Fond Du Lac		Normal	03-06	02-107	Tap repair	132.5	Not bid	5/7/2010
Kenosha Hills	4899 Fond Du Lac		Normal	03-06	02-107	Tap repair	133.1	Not bid	5/7/2010
Kenosha Hills	4899 Fond Du Lac		Normal	03-06	02-107	Tap repair	148.0	Not bid	5/7/2010
Kenosha Hills	4911 Fond Du Lac		Normal	03-06	02-107	Tap repair	231.2	Not bid	5/7/2010
Kenosha Hills	4911 Fond Du Lac		Normal	03-06	02-107	Tap repair	283.2	Not bid	5/7/2010
Old Hickory	3233 Brookfield		Normal	16-99	16-103	Bad tap, mud	84.0	Not Bid	11/10/2009 Also 9/28/12
Old Hickory	3211 Brookfield		Normal	16-99	16-103	Repair section (possible 2 taps)	177.0 - 186.5	Not Bid	11/10/2009 Also 9/28/12
Powers Place	10077 Kimberly Ln	08-164	Emergency	05-02	01-22	Bad tap & RIJ	252.1 252.4	Not Bid	1/24/2008
Powers Place	10077 Kimberly Ln	08-165	Emergency	05-02	01-22	Crack in pipe	309.0 (approx 2.5' past MH 01 22)	Not Bid	1/24/2008
Rustic Hills	6588 Center Ridge Rd	08-91	Emergency	20-162	20-163	Tap, L, roots/hvly	95.8	Bid 2/22/08 Moved to future	10/12/2007 3/14/2008
Rustic Hills	6599 Valley Rd	08-92	Emergency	20-162	20-163	Tap, R, roots/hvly	155.0	Bid 2/22/08 Moved to future	10/12/2007 3/14/2008
South Broadview	5366 E Timberwood (Bid as 5388 E Timberwood)	08-201	Emergency	14-54	14-55	Tap, maybe hammer/root	60.8	Bid 2/26/08 Not approved	2/21/2008
South Broadview	7411 Marywood	08-131	Normal	14-179	14-181	Bad tap, roots	236.7	Not Bid	7/19/2007
Springston	Carmona Dr.		Normal	12-08	12-09	Lateral connection problem	35.1	Not Bid	5/14/2014
Springston	Carmona Dr.		Normal	12-08	12-09	Lateral connection problem	94.0	Not Bid	5/14/2014
Springston	Carmona Dr.		Normal	12-08	12-09	Lateral connection problem	122.1	Not Bid	5/14/2014
Springston	Carmona Dr.		Normal	12-08	12-09	Lateral connection problem	303.1	Not Bid	5/14/2014
Springston	Carmona Dr.		Normal	12-08	12-09	Lateral connection problem	311.1	Not Bid	5/14/2014
Springston	Carmona Dr.		Normal	12-08	12-09	Lateral connection problem	359.5	Not Bid	5/14/2014
Stonegate	8366 Stonegate Dr	08-167	High	11-134	11-199	Dropped pipe	173.2	Not Bid	1/30/2008
Sudamar Hgts	5366 Oakwood		Normal	20-16	20-17	Lateral connection problem	98.8	Not Bid	7/17/2013
Sunrise Manor	4822 Hwy 261/8141 Alexandria (complaint)	08-216	Normal	11-283	11-192	8" main line repl. &/or slipline	Entire line	Not Bid	2/29/2008
Tennyson Terrace	7877 Owens		Normal	15-51	15-50	Hammer tap L 10:00	123.0	Not Bid	7/28/2011
Tennyson Terrace	7877 Owens		Normal	15-51	15-50	Hammer tap 12:00	204.0	Not Bid	7/28/2011
Tennyson Terrace	7899 Melody Ln		Normal	15-58	15-59	Offset jnt, water	281.0	Not Bid	11/19/2009
Tennyson Terrace	7922 Lincoln Ave	08-207	Normal	15-59	15-58	Protruding tap	306.9	Not Bid	2/27/2008 11/19/2009
Tennyson Terrace	7833 Melody	08-136	Normal	15-60	15-59	Bad tap, top, roots/lt	265.3	Not Bid	8/9/2007

SUBDIVISION	ADDRESS	PROJECT NUMBER	DEG 1-10	MH#	MH#	REPAIR NEEDED	FT LOC	STATUS	TV DONE
Tennyson Terrace	7855 Melody	08-137	Normal	15-60	15-59	Bad tap, L, mud	290.6	Not Bid	8/9/2007
Town	1101 Hwy 662		Normal	06-45	06-46	Tap L 10:00 50% rts	8.0	Not Bid	11/19/2007 5/25/2012
Town	1025 Hwy 662		Normal	06-45	06-46	Tap L 10:00/30% rts	49.0	Not Bid	11/19/2007 5/25/2012
Town	1007 Hwy 662		Normal	06-45	06-46	Hole in jnt/rts & soil	258.0	Not Bid	5/25/2012
Town	Clark Street		Normal	06-57	06-58	Lateral connection problem	4.0	Not Bid	9/10/2014
Town	Clark Street		Normal	06-57	06-58	Lateral connection problem	211.6	Not Bid	9/10/2014
Town	Clark Street		Normal	06-58	06-57	Lateral connection problem	91.5	Not Bid	9/10/2014
Town	508 Water St		Normal	09-02	09-03	Tap 10:00, offset mod/dirt	60.0	Not Bid	3/21/2012
Town	507 Water St		Normal	09-02	09-03	HT 12:00	82.0	Not Bid	3/21/2012
Town	Water & Plum	08-64	High	09-11	09-12	Offset joint	139.9	Re-bid 2/13/08 Moved to future	7/13/2006 1/29/08
Town	510 West Jennings	08-142	High	09-12	09-11	Protruding tap	27.5	Not Bid	2/12/2007 1/29/08 2/4/08
Town	Sycamore		Normal	09-94	09-95	Lateral connection problem	50.5	2015 Paving Proj.	4/8/2013
Town	Sycamore		Normal	09-94	09-95	Separated Joint	60.5	2015 Paving Proj.	4/8/2013
Town	305 E Jennings		Normal	09-117	09-98	Crack (2 ft)	53.3	Not Bid	12/4/2013
Town	305 E Jennings		Normal	09-117	09-98	Crack	173.3	Not Bid	12/4/2013
Town	314 Hillcrest Dr		Normal	09-133	09-134	Lateral connection problem	0.5	Not Bid	5/16/2013
Town	314 Hillcrest Dr		Normal	09-133	09-134	Jnt - Infiltration	152.5	Not Bid	5/16/2013
Town	618 Treelane		Normal	10-101	C.O.	Repair tap R 80% rts	393.0	Not Bid	11/15/2010
Town	Vet Clinic on 261		Normal	10-146	10-145	Point repair	32.0 - 38.0	Not Bid	4/19/2010
Town	Vet Clinic on 261		Normal	10-146	10-145	Hammer tap 12:00	62.0	Not Bid	4/19/2010 11/26/2012
Town	Golden Budda		Normal	10-146	10-145	Hammer tap 12:00	188.0	Not Bid	4/19/2010 11/26/2012
Town	Golden Budda		Normal	10-146	10-145	Crack in main/min. dep.	214.0 - 218.0	Not Bid	11/26/2012
Town	General Denistry/Robin Hill		Normal	10-146	10-145	Hammer tap 12:00	241.0	Not Bid	4/19/2010 11/26/2012
Town	Golden Budda		Normal	10-146	10-145	Hammer tap R3:00	481.0	Not Bid	11/26/2012
Twin Oaks	7411 Oak Park	N/A	Normal	14-141	14-140	Tap 12:00 (sad)/20% rts at conn & 60% up in lateral	290.0	Not Bid	11/27/2012
Twin Oaks	7443 Oak Park	N/A	Normal	14-141	14-140	Tap L10:00 (Sad)/rts 20% at conn	371.0	Not Bid	11/27/2012
Twin Oaks	7446 Oaklawn	08-157	Normal	15-121	15-122	Tap/offset	1.0	Bid 7/15/08 Not approved Will need rebid	11/14/2007 3/2/2010
Twin Oaks	7466 Oakdale		Normal	15-121	15-122	Hammer tap R 3:00	95.0	Not Bid	3/2/2010
Twin Oaks	7455 Oaklawn or 7442 Oakdale	08-158	Normal	15-121	15-122	Tap repair	169.2	Bid 7/15/08 Not approved Will need rebid	11/14/2007 3/2/2010
Twin Oaks	7400 Oakdale		Normal	15-121	15-122	Crack in main	308.0	Not Bid	3/2/2010
Twin Oaks	7433/7411 Oaklawn	08-160	High	15-121	15-122	Point Repair	311.5	Repair done 2009	11/14/2007
Twin Oaks	7399 Lenn Ln	08-156	Normal	15-132	15-133	Protruding tap, left	194.9	Not Bid	2/21/2007
Woodstone	Woodstone Dr		Normal	07-48	07-49	Lateral connection problem	95.2	Not Bid	10/8/2014

NOTE: These repairs are also listed under possible future repairs - Sanitary sewer problems identified but not yet repaired.